

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XIX - NUMBER 2 - NOVEMBER/DECEMBER 2000



Dear Members:

Holiday Greetings from Dug Waggoner (#10) and myself from the San Francisco Bay area. Dug is our Art Director and responsible for the nice look of this magazine. We send you our best wishes for the New Year.

Our membership is down from the record high of 642 paying members as of August 31. Our membership now stands at 535. This is always the way it is after renewal time. Two thirds renew and one third do not. Some have sold their cars or do not plan to renew, but most have just forgotten. I will send them a reminder letter in January.

We made a mistake on the cover of the last issue. The volumn number and date read:

VOLUME XVIII NUMBER 6 JULY/AUGUST 2000
It should have read:

VOLUME XIX NUMBER 1 SEPTEMBER/OCTOBER 2000

We have printed and enclosed a corrected "patch" for you to use. Please use this to make this correction to your copy. Torque Tubes mailed out after the first mailing in late October have already been corrected. We apologize for our error.

The 1937/38 Buick Story has just been pub-

lished by Walt Bruegger (#1444), one of our members. The 124 page contains book over 100 original ads Buick used to publicized their cars. The book also covers the course of events which would go on to make these two model years among the most desirable to Buick collectors. If you're


interested, the book costs \$30 postpaid in the US. Add \$5 for foreign orders. To order, send check or money order to Walter Bruegger, 2432 Bridwell Way, Hayward, CA 94545.

For those members who live in the San Francisco Bay area, the *Howard Jones Battery Company* in *Belmont, CA*. Phone: (650) 591-1726. will give a discount on 6 volt batteries for our old cars. Tell them you're with the Buick Club (*BCA or 37/38*). They charged me \$72. plus tax for a size 2E, 40 months, 650 amp battery. Call first to make sure they have your battery size in stock.


When I picked up the battery, I spotted a 1937 Buick Special Sport Coupe with jump seats Model 46S in a nearby garage. It had a 1936 steering wheel with an ivory colored horn button and was painted dark gray, its original color (*Paint No. 505*). It was an early Flint assembled car with Body Number 33. The firewall data plate had the date of manufacture filled in, 11-23-36. *Bob Lawrence* (#653)-Ohio's 1937 sedan was assembled one day later on 11-24-36. These are the only two Buick data plates I've ever seen with the build dates filled in.

While coming out of a castle last Septem-

ber in the small German town of Wewelsburg, I spotted this cute red English sports car whizzing by. The car had German license plates, but also English ones. The driver and passenger were wearing aviation style leather caps and goggles. What a sight! Everyone stopped









what they were doing to take a look!

Buick offered these chrome wheel rings on

1936 and 1937 Buicks. They are listed in the 1937 Accessory catalog, but not in the 1938 one. I believe they did not sell well and were dropped for 1938.


This is what the 1936 rings looked liked (top of page 3). They had clips on the back that snapped into the holes in the steel artillery rims used that year. Thanks to Greg Field (BCA #1) for letting me photograph his ring at the BCA Western Regional Meet in Sacramento, CA last September.

The next photo shows an attractive dark blue 1937 McLaughlin Roadmaster Model 81 belonging

to Nigel Leedham (#1498) in British Columbia, Canada

This beautiful brown 1937 4-Door Slant-Back Sedan Model 47 belongs to Lewis Jenkins (#1085) in North Carolina (middle photo). It was photographed by Gene Stewart (#1457) when he visited Jenkins Restoration Shop last year.

Jim Terruso (#816) in Massachusetts has been rebuilding the engine of his 1937 Century sedan. (bottom photo) The engine was bored .030 over. He used a '39 Buick cylinder head



= TORQUE TUBE=

You can now find your '37-'38 Buick Club on the World Wide Web: http://www.classicar.com/clubs/buick/buick.htm


The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Printer Liaison: Bill Olson, #427
Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE







with dome pistons. Insert bearings were installed and the engine was balanced. He also used a '52 Buick oil pump for more flow. Jim says the engine runs quiet and smooth!

Irv Heckert (#940) in Pennsylvania sent this photo of his 1937 Special Sedan Model 41. (top of page 4) He recently started restoring it. The wheels are sand blasted and painted. He got a local Amish buggy maker to do the wheel pin-striping. Then he installed a new set of Firestone Champion wide white-wall tires and tubes. Hopefully Firestone won't recall his new tires because of tread separation!

Brothers Doug (#51) and Marshall (#370) Nelson in Salem, Oregan, have owned these two cars (bottom of page 4) for years. Doug restored the black '38 Century Coupe







and Marshall the red '37 Roadmaster Phaeton. They are a familiar sight in the Salem area.


Last September these two sidemounted '38 Special Model 41 Sedans took part in a community parade in Newark, CA (San Francisco Area). That's Mark Garcia's (#1390) blue sedan leading the way followed by Don Howell's (#559) dark grav one. (top of page 5) After the parade, they both drove over to the Buick dealer in San Jose to display their cars along with about 20 other antique cars from the local Buick Club. I was impressed by a Buick I had never seen before, a beautiful, long 130" (3.3 meters) wheelbase open 1915 Touring Sedan.

Buick historian Terry Dunham in Florida is the coauthor of the book: BUICV- A Complete History. Now Terry needs your 1937 or 1938 Buick frame (serial) number for a research project on our cars which will be published in a future Torque Tube. Every possible serial and model number that can be ob-

tained will be needed to successfully complete the project. For example: Model 38-46C, Serial No. 13312269. Send to:

Terry Dunham
PO Box 4057 Apopka
Florida 32704-4057.
E-mail: BuickOHV@aol.com
Thanks.

Terry was also responsible for organizing the first and second *Buick Club of America (BCA)*National Meets in Flint, Michigan in 1971 and



1972. Reflecting back on those days long ago, Terry writes:

"The 1972 Flint Meet was the second Flint National (actually any kind of a national period) for the Buick Club. My wife and I had organized and directed the very first one a year earlier from

our home in California. As I look back over the years, I simply do not understand how we were able to accomplish what we did, especially in 1971."

"There was virtually no one to help us. The Buick Town chapter did not exist. We flew back with a dream that was a lot more art than science, and managed to pull the thing off. We recruited Judges on the spot. Since the Buick Club had no judging form, we used an AACA form that had been filled out in ball point on a car that had been judged some three weeks earlier. One of the secretaries at the Buick Public Relations Department



took the form, used whiteout on all the ball point numbers and vehicle information, and ran 200 photo copies. They were used as the first judging forms. Ah me, when you are young, you just plain don't know that it can't be done!"

This 1937 dated Hindenberg

nir of the arrival of the German airship. Unfortunately this arrival was not to be. The airship exploded, probably due to static electricity the flammable hy-

recently painted pennant was sold in Lakehurst, NJ as a souve- 1937 Special Sport Coupe Model 46S that he pur-

> chased from Dave Tacheny (#997). The car is now painted Sudan Blue, a light blue color that looks especially beautiful on coupes and convertible coupes. The car is shown at the National Museum of Transport in Cali. Colombia. That's Jose's AT6-D Texan Trainer W.W.II airplane behind the car.

Recently the door-

bell rang and when

I answered it there

was losé and Stella

Pardo (#558) from

Cali, Colombia in

South America.

This photos shows

my wife Margo,

José and Stella be-


hind my '38 Cen-

tury coupe. On

page 6 is Jose's

This photo of a 1937 Flxible Buick Ambulance appeared in the book "Classic American Ambulances" by Walt McCall and Tom

Hindenburger a n d drogen in her airbags. I purchased this pennant at a local antique show. I plan to display it with my '37 Century coupe at a future car show.





McPherson, published by Iconografix, 1999. Apparently the Flxible company was quite fond of Buick chassis as there are quite a few Buicks in this book. The photo caption reads: "A proud owner takes deliver of his new 1937 Flxible-Buick Ambulance at the Flxible factory in Loudonville, Ohio. The Flxible ambulance body is mounted on a 1937 Buick Special chassis. Note the dazzling white paint job which is complemented by the extra-cost white sidewall tires and the fog

lamps mounted on the front bumper."

Keith Korbut (#1025) in Springfield, MA is the Buick Club of America (BCA) Technical Advisor for 1937-38 Buicks. He says he gets quite a few e-mails from countries all over the world. Thanks for supporting 37/38 Buicks Keith.

He has also been busy with a new museum he opened in Springfield. Its dedicated to automobiles built in Springfield MA and also transportation related items. Its keeping him busy. The mu-



seum is called the *Duryea Transportation Society Museum* and it's located at 25 Mill Street Springfield, MA 01108. All our members are welcome to stop by.

Gene Mousel (#1432) in Tacoma, WA recently purchased this dark green with red wheels 1938 Cen-

tury Coupe from Jeff Truttman in Southern California. He has been fixing a few details and enjoying his new car.

Jack Provan (#1307) in Melbourne, Australia reports that in early October, he and some friends drove 500 miles (800 km) to Adelaide to at-

tend the Bay to Birdwood Car Meet. He drove his '38 Holden-Buick Century sedan (below). The others drove a '41 Packard, '41 Buick coupe and a '68 Buick convertible coupe. It took 2 days to get there. They spent 3 nights there and with 1,600 other cars traveled 30 miles to the Birdwood Mill. It was a great day to be with so many other old cars. The following morning he and his friends returned to Melbourne along the coastal road. They spent 3 nights at popular resorts along the

way. Great weather and good company made for an enjoyable trip.

The 1937-1938 Buick Eastern Club Meet will be held June 6-8, 2001 in Gananoque, Ontario, Canada. This is on the Canadian side of the St. Lawrence river. The Provincial Inn Motel in Gananoque will be our base

as we explore some natural wonders, some Canadian countryside and a little bit of history. We will visit Kingston and tour Old Fort Henry, then move inland to a small artisan village to explore and shop. On our way back we'll stop to view a private mu-

Finally we'll hit the water, a cruise of the 1000 islands with a stop at a turn-of-the-century castle. Our hosts will be **Bob and Doreen Ward** (#114). Make your reservations directly with the **Provincial Inn** in Ganacque. The toll free number is **1-877-837-7768**. Call during office hours, 9-4 EST, and be sure to mention the **1937-1938 Buick Club** to get our special rate of approximately \$42 US plus tax. A block of rooms are being held until April 15.





After over a decade, *Bill Rossitier* (#947) of Riverside, CA has completed the restoration of his 1938 Roadmaster Sedan. The light gray Roadmaster won first prize at the *Buick Western Regional Meet* held in Sacramento, CA in September, 2000.

A ROADMASTER Restoration

By Bill Rossitier (#947)-Riverside, CA

My 1938 Roadmaster 4-Door Sedan Model 81 was delivered new in Mexico City where it spent most of its life. After the original owner's death, the car was given to his nephew who lives in the Los

Angeles, CA area. The car was then shipped to Tijuana, Mexico on the border with California. The nephew then drove the car from there to Rosemead, CA (Los Angles area) and left it at a friends house.

And that's where I first saw it one day in 1989 while driving to work. The car was painted white and inside a fenced yard with a guard dog. So I couldn't just walk up to the door to inquire about

it. I worked for a Title Insurance Company, so I was able to get the home owner's phone number. He was quite helpful because he rented the house and wanted the old car off his property.


By calling the renter, I was able to get the car owner's phone number.


After several weeks of negations, we agreed on a price and I became its third owner. It had rust

in the trunk, doors and rocker panels and the motor needed rebuilding. And many of the parts were missing.

Luckily I knew Frank Guildner of Sunland,







CA had a '38 Roadmaster parts car. Greg Field (BCA #1) also supplied many hard to find parts. And of course I got a lot of parts help from Dave

Tacheny (#997) in Minnesota.

The car had a body-off-the-frame restoration. The engine was rebuilt by Gerry (pronounced Gary) Duttweiler in Ventura, CA. Actually, he rebuilt the first engine rebuild that was badly botched by a local machinist. In fact, a

large part of Gerry's business comes from correcting and cleaning up the work of others. He's an expert on rebuilding Buick engines and did an excellent job!

Gerry also engineered a full flow oil filter installation. A Gano coolant filter was added (as suggested in Vol. XII, No. 6, July/August, 1994 TT). Dual intake and exhaust manifolds with tandem dual 1953 carburetors, dual point ignition, later timing chain cover with neoprene instead of rope seal were also installed.


Machine work on the engine included head milled 100 thousandths (0.1 inch or 2.5mm), block decked (surfaced) 30 thousands (0.03 inch or 0.76


mm) and cylinders bored 30 thousands (.03 inch or 0.76 mm) over.

Les Randolph of Brocton Auto Clinic in Riverside, CA was of great assistance. He helped me with rebuilding electrical connections and switches, bending brake and fuel lines, installing door insu-

lator rubber and a whole lot of good advice. The light gray Roadmaster won first place at the October, 2000 Buick Western Regional Meet in Sacramento, CA. It received 195 points out of a possible 200.

The car looks beautiful..... a far cry from when I first saw it eleven years ago!





The car looks beautiful....a far cry from when I first saw it eleven years ago!

purchased it around Christmas in 1953 when I was 15 years old. My dad drove Buick Centurys and loved to be challenged, especially on Western Maryland mountains. It was many years before anything was built that could out-perform a properly prepared Century.

My dad was strict and certainly wouldn't allow me to hitchhike. He worked for the Maryland State Highway Dept. and was responsible for road conditions. One snowy Saturday morning my father was out checking on the

roads. He phoned to tell me a used car lot in Cumberland, MD had a 1937 Century Convertible for sale. I replied: "How can I get there?" To my amazement my father said hitchhike a ride. Believe me, I did immediately.

I bought the Buick. The firewall data plate says it's Body No. 137, Paint No. 503 Maroon and came with Red Leather upholstery. The car



By Charlie House-Maryland


(ED: Thanks to Charlie House in Maryland for this story. Last year he sold his '37 Century convertible after owning it for over 46 years!)

still has the original red leather.

My home was out in the country and many of the roads were unpaved. I drove it occasionally without a license until I graduated from high school in1956. At that time I was 17, left home, and went to work in Baltimore, MD leaving my Buick covered at my parents home. I started restoring it in the 1960's, but became side-tracked



I owned this maroon 1937 Century Convertible Coupe Model 66C for over 46 years.




with Studebaker Speedsters, Hawks and Avantis."

In the 1970's I started restoration again, this time removing the body from the frame. Not much mechanical restoration was needed because it still only has 87,000 miles on it. I rebuilt the suspension, replaced the clutch assembly, valve job, timing chain and of course the brakes

and a new wiring harness.

It was refinished and finally assembled in the mid 1980's. It was repainted with maroon lacquer. The top is Hartz (tan) with maroon piping. Stainless moldings are original. Bumpers, guards and top bows were re-chromed. The restoration is holding up very well.



I have owned many antique and special interest cars, most of them 1935 to 1987 Buicks. In fact the 1936-46S Sport Coupe in the North Dakota Highway Patrol Museum in Bismarck was previously mine. There has to be something significant about a car like this 37-66C that makes you keep it for over 45 years. Those early Buick Century's were cars with personality and performance!






He purchased it in California about 10 years ago and has traced the ownership back to the 1950's. He even had a visit from the then owner who filled him in on some of the car's history including being used for racing! (Note: '37 convertible coupes originally came with a rear window with a vertical bar in the center).

MY BROTHER'S '38 CONVERTIBLE

By Harold Cohen (#1322)-Englewood, CO



Here I am leaning on my older brothers 1938 Special Convertible Coupe Model 46C. He bought it from the son of the owner of the Denver Buick Company when it was only a few months old. The black car came with red wheels and a red stripe on the top of the doors where you rest your arm. It also came with a tan top and the accessory grille guard. Note the shape of the original rear window. It's like the '37 window except without the vertical bar in the center. The back of this photo is dated June 16, 1938 as shown in the inset above.




Here I am again leaning on a '38 Buick Special Convertible Coupe. Only this one belongs to Harry Logan (#651) in Los Altos, CA. I visited him on a recent trip to San Francisco. We took a cruise around his neighborhood and riding around in a '38 convertible brought back a lot of memories!

The back of this photo is dated June 16, 1938.



When my brother went into the Army in 1942, I got the car. One day while backing up, I hit a water faucet on the side of our house and put a deep crease in the passenger side door. It was repaired and repainted for \$15! After my brother returned home from the army, he traded the '38 Buick in on a new 1946 Chrysler coupe.



My sister also used the car. She is short and could barely see out. While driving the car, she was hit by a streetcar. The damage came to \$125. When she got her insurance check, she bought herself a fur jacket instead of fixing the car!

1937 & 1938 BBJJ CELS SEEN AT HERSHEY


By Andy Diem (#852)-Washington, DC



This 1937 Special 4-Door Slant Back Sedan Model 47 was driven to Hershey and hopefully home.



I am not certain if the roof rack is an original option. Looks like the radio antenna is a later addition.



This 1937 Century Convertible Sedan Model 60C had a beautiful older restoration. It sold at Hershey. Hopefully the new owner will join our Club.



This red1938 Roadmaster Convertible Sedan Model 80C was offered at \$35,000. It was also for sale at last year's Hershey.



1937 & 1938 BUICK HEATERS

By Harry Logan (#651)-Los Altos, CA



Buick offered two hot water heaters, a Master and DeLuxe model in 1937 and 1938. Shown above are the 1937 Deluxe and 1938 Deluxe heaters. This 1938 heater also has the extra cost defroster motor installed on top.

Install a New Buick Heater

before the first frost

* Two new, improved Buick heaters, for the 1936-37 season, are now available. New type construction, advanced features, and greater efficiency make these the finest heaters we have ever offered. The quicker, quieter summer warmth of either will be just as welcome during the fickle frosts of fall as it will be next winter. Drive in today, drive out equipped for any drop of the mercury.



Now Baile To Law House, Jin's: New rulds how commencing sizes nomently high bearing convery. Compact mond sait. New definition and from worned opining provab being are circulated. New sensible speed control gloss orifly when heater is amond on. Imposed the and moint—quarter, with her lasticis draw.



Mos Mac & "Moste" Record, \$11.55. Some high quality and advanced destance of "The Lane," but with fin immed of ordicase, Summed toward in best major, lefed for compet in one wanther fire our mended for off years in more manderate disease.

This 1937 heater ad shows both the Deluxe (top) and Master heaters. Between the two plastic knobs is a chrome strip with either Buick Master or Buick Deluxe on it. The plastic knobs allow you to swing out the two doors to aim the heat.




This '37 Deluxe heater had a radial core while the Master heater had a smaller flat core, a smaller case and about 10% less heat capacity than the Deluxe model. It's recommended for coupes or cars in moderate climate areas.

Notice the plate on top. Remove it to attach the defroster which cost extra. If you have a heater and want the defroster, you'll need to buy a defroster motor. '37 and '38 defroster motors are not interchangeable, so be sure to get the correct motor for the year of your heater. A '37 defroster motor will fit either the '37 Master or Deluxe model. A '38 defroster motor will fit either the '38 Master or Deluxe Model.



And you'll also need to buy a pair of defroster ducts like these. The '37 duct is on the left, '38 on the right.




In '37, part of the duct mounted on the top of the dashboard (above) and directed the hot air to the bottom of the windshield. The lower part mounted under the dashboard where the hoses from the defroster motor attached. I have seen various other typed of '37 ducts but these were the factory ones. Some '37 Buicks only have the driver's side defroster.

On '37 Special and Centuries, the deflector part of the '37 duct that mounts on the top of the dash was painted dark brown like the steering column, ashtray, map light cover and radio plates. I believe the '37 Roadmaster and Limited


deflectors were painted the color of the dashboard, either black, light gray or mahogany. The ducts shown were on an un-restored '37 Limited and were light gray like the dashboard.

If the '37 Buick was ordered without a defroster, two woodgrained snap-on tops were used to cover the two long rectangular slits in the top of the dashboard where the hot air comes out.

In '38, the hot air came out two openings at the bottom of the windshield garnish molding, one for the driver and one for the passenger. So no deflector ducts were mounted on top of the dashboard as in '37.



But you still need ducts under the dashboard for attaching the flexible defroster hoses as shown in this ad.




This is how the '37 heater was installed. The '38 was installed in a similar manner. Note the foot warmer openings under the heaters.



The heater and defroster variable speed switches mount under lip at the bottom of the dashboard. I believe the heater and defroster switches on the right with ivory colored knobs came with Buick heaters. They have a #51 light bulb in them and light up when on. They mount through holes in the lower lip of the dashboard. The shape of the knobs are different so you tell if you're operating the heater or defroster. I've also seen mahogany colored heater switches. They mount differently and hang several inches below the bottom of the dashboard. The switches on my '38 Special and Century mount to the left of the steering column in easy reach of the driver.

One member reports seeing two unrestored '37 Roadmaster's with the variable speed switch for the heater to the left of the driver and the defroster switch at the other end of the dashboard. This location would make it difficult for the driver to operate and may not be factory installed.



Buick also offered a hot air heater in '37 & '38. They were for very cold climates. Fresh outside air, drawn through the radiator, was forced through a heating unit and circulated throughout the interior of the car. It was much less popular than the hot water heater. My Accessory List indicates the hot air heaters were "Only available for direct shipment from Factory at Buffalo."



The 1937/38 Buick Story





Send check or money order for \$30 (per book), made payable to "Walter Bruegger"

and sent to:

Walter Bruegger 2432 Bridwell Way Hayward, CA 94545 Welcome to 24 months of power-packed drama when new 1937 and then 1938 Buick blazed a path of demand and glory across the America consciousness.

TOTAL COST: just \$30 per book (includes 1st class postage) FOREIGN ORDERS please ADD

This is the complete story of the 1937 and 1938 Buick during the 24 month period when they were available brand new to the buying public. Containing over 100 original ads from those two classic years of Buick style and beauty, this "must-have" book goes beyond being only a collection of the dynamic ads Buick ran in both national and local newspapers and major periodicals during those glory years. The book also covers in great detail the course of events that would go on to make these two model years the most "classically" regarded of all collected Buicks.


Don't delay, order today!


YOUR 1937 OR 1938 BUICK SERIAL NUMBER IS NEEDED!

Serious historical researcher needs your 1937 or 1938 Buick frame (serial) number for a research project.

Please take the frame number directly off the vehicle as documents are often incorrect.







The 1938 serial number is under the hood on the frame near the starter.

Mail the frame number, the year of your Buick and its model number ie: 41, 66C, 81 or 90L etc., to:

Terry Dunham

PO Box 4057, Apopka, Florida 32704-4057 · E-mail: BuickOHV@aol.com

Information collected will be used to determine how Buick assigned serial number blocks in 1937 and 1938. Conclusions developed will be summarized and shared in an article to appear in a future Torque Tube. Every possible serial and model number that can be obtained will be needed to successfully complete the project. Thanks!

TERRY DUNHAM-BUICK HISTORIAN

New Members

William Malloy (#1539) 64 Jean St. Framingham, MA 01701 38-66S

Don Smith (#1540) 30 Harrison Heights Selah, WA 98942

David Corsi (#1541) 6 Anna Ct. Novato, CA 94945

Bruce Campbell (#1542) 1462 Paseo Nogales Alamo, CA 94507 37-41 Harold Mueller (#1543) 210 Kent Rd, Lakeland, FL 33809

Carl Costantino (#1544) 312 Prospect Ave. Erial, NJ 08081 38-41 Bill Bailey (#1545) 7207 Roundrock Rd. Dallas, TX 75248 38-46 Vernon Dolleck (#1546) 10730 Pacific St. Suite 242 Omaha, NE 68114 37-81

Phillip Murelaga (#1547) 2515 Bruins Cir. Boise, ID 83704

Ron Moreland (#1548) 4745 Mouse Creek Rd. N.W. Cleveland, TN 37312 38-48

Francis Kredit (#1549) 2319 S. Redwood Dr. Anaheim, CA 92806 37-61 Rob Whitson (#1550) 15510 SE 133rd St. Renton, WA 98059 38-46S

Walter McCall (#1551) 2281 Victoria Ave. Windsor, Ontario Canada

Jon Mathisrud (#1552) 1860 Hunter Lane Mendota heights, MN 55118 37-66C

Bayard Guild (#1553) 11 Main St. Dover, MA 02030

Richard Bowman (#1554) 1921 Edenville Road Chambersburg, PA 17201

Jerry Neal (#1555) 13750 E. Palomino Dr. Fort Lauderdale,FL 33330 37-46C

Back Issues Still Available!

The following Back Issues of the Torque Tube are available for \$4.00 each postpaid in USA and Canada. All other countries \$5.00 per copy.

- 1991-1992 Volume X Numbers 1, 2, 3, 4, 5, 6, 7, 8 & 9
 - 1993-1994 Volume XII Numbers 6
 - 1994-1995 Volume XIII Number 6
 - 1995-1996 Volume XIV Numbers 3 through 6
 - 1996-1997 Volume XV Number 5 & 6
 - 1997-1998 Volume XVI Numbers 1 through 6
 - 1998-1999 Volume XVII Numbers 1 through 6
 - 1999-2000 Volume XVIII Numbers 1 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

Parts FOR SALE

PARTING 1937 AND 1938 BUICKS

The following is just a portion of what's available. Call with your needs.

The following is just a portion of what's available. Call with your no	eeas.
• 1937 PARTS	6200
AA-1 Stromberg carburetor, complete	
Coune & convertible coune seat	5200
Accessory grille bug screen, good condition	
Century 3.9 gears, excellent condition	
Grille, reproduction	
Century wheels., excellent condition	\$100 each
Parts radio	
40/60 Series rear brake cables, good condition	\$40 pair
Master and deluxe heaters	\$75 each
Century radiator	575
Special radiator	575
Rear springs 40 & 60, good condition	\$100 pair
Radio delete plates	\$15
Small series throttle linkage	\$25
Big Series rocker assemblies	\$50
Fender lights	\$65 pair
Trunk lights, complete	\$50
Tail lights with lenses, all series	\$50 pair
Tail lights with lenses, all series	\$50 pair
Wiper transmissions	50 pan
Special manifold	
Throttle cable	¢100
Special transmission	\$40 mair
Special splash pans	540 pair
Century hood.	5100
Headlight switch	520
Radio grilles	
Wiper motors	
Trunk hold-up arms	\$20
Sun visors	
Bumpers	\$40 each
Bumper arms	\$15 each
Steering wheel	\$50
40 & 60 running board brackets	\$50 set
Buick creast badge for hood trim strip.	\$50
Gas pedal	
Small and large series generators	\$75
• 1938 PARTS	
AAV-1 Stromberg carburetor, complete	5200
Coupe and convertible coupe seat	\$200
Heater defroster motors	
Special right sidemount fender, complete	5400
Large series wiper motor	
Hubcaps, restorable	\$25 each
Special hood hinge	\$100
NOS left taillight housing and base, no lens	\$50
Century motor, complete long block	\$500
Century motor, complete long block	

	Century hood tops and side panels
	Fender lights
	Limited door sills
	Breather tubes
	Trunk hold-up arms
	734Z starter with solenoid\$50
	Special hood lettering
	Defroster ducts
	Wiper transmissions
	Rear license plate stand, bracket & light for sedan\$45
	Tail lights, complete
	Assist straps with screws
	Throttle cable
	Special radiatorS75
	Battery tray
	Special manifold, complete
	Special hood sides & tops
	Century radiator
	Special Lynn Steele runningboard rubber
	Used 5 post valtage regulators
	Used 5 post voltage regulators
	NORS voltage regulator, new in box
•	1937-1938 PARTS
	Large series transmissions
	Special sidemount covers, complete
	Special air cleaners
	Radio hanger brackets
	Large series flywheel with good teath
	Big Series spark plug cover
	Headlight buckets
	Large series fan belts, new
	Map light switches
	Small series spark plug covers
	Rear fender splash aprons
	Big Series manifold ends
	16" beauty rings
	Headlight bezels
	Trunk hinges
	Front arm rests
	40 & 60 rear vent windows, need plating
	Rear view mirrors
	Special rear motor mounts
	Century rear motor mounts
	40 & 60 4 dr. sedan doors
	Front vent window frames & mechanisms
	Rig Series fuel nump cores
	Big Series fuel pump cores
	4-Post voltage regulator, used
	15" Beauty rings
	Headlight adjusting buckets\$100 pair
	Front license plate bracket
	Dave Tacheny (#997)
	11949 Oregon Ave. N.
	Champlin, MN 55316
	(612) 427-3460
	763

(Parts For Sale continued from page 25)

• 1938 SPECAIL MODEL 41 PARTS FOR SALE: MAKE OFFER No reasonable offer refused.

- · Fuel Pump
- · Complete Carter Carb. used with starter switch
- Starter
- · Transmission, 3 speed, partially disassembled
- · Radiator
- Gas tank with sending unit
- · Front bumper with brackets
- · Rear bumper with brackets
- · Hood
- · Front nose
- · Right Side panel
- · Left side panel
- · Some side chrome
- · Complete Rear End and Torque tube
- Bumper Guard
- · Horn
- · License plate holder
- · License plate bracket
- · 3 Inside door handles with mechanism
- · 2 Inside window handles
- · Vent window handle with mechanism

- · Radio Knob
- Speedometer and gauge cluster for dash
 - · Bright light switch
 - · Parking light lenses, plastic
 - Headlight switch
 - · Headlight ring
 - · Ashtray
 - · 2 taillight gaskets
 - · Wiper holder
 - · Dome light cover
 - · Radio antenna with cable
 - · Windshield washer kit
 - Distributor
 - · Dole temperature control valve
 - · 2 rear shocks
 - · 2 rear springs
 - · 2 front drums with bearings
 - · Rim
 - · 2 sets of generator brushes, new
 - · 2 sets of starter brushes, new
 - · Some literature

Make an offer for all or some of these parts. Please call between 6:00p.m. and 9:00p.m. CST

John Gillio (#1016)

15329 Ridgeland, Oak Forest, Illinois 60452

Phone: (708) 687-4303 E-mail: jondon17@prodigy.net

1937 PARTS FOR SALE: MAKE OFFER

1937 Roadmaster front brake drums and front spindles.

Doc Scantlin (#1150) 2824 Ridge Road, Huntingtown, MD 20639

Phone: (301) 855-9102 E-mail: doc@docscantlin.com

Parts WANTED

1937 PARTS WANTED:

For 1937 Buick Special need:

- Both wind screen (windshield) glass & rubber (does not have to be good as long as its useable).
- · Gear shift knob.
- · Two rear window rubber seals, usable.
- Four rubber door seals in usable condition.
- One passenger side rear vent rubber seal.

I know I can purchase new rubber seals but I am putting this car back on the road on a shoe string budget. Thank you.

Mal Oneill (#1425)

78 Williams St.

Bishop Auckland

Durham County

England DL14 8RJ

E-mail: buickmal@lineone.net Telephone: 44 0138 860 2800

1938 PARTS WANTED:

For 1938 Roadmaster Sedan Model 81 need:

· Front drums and hubs

(12 inches diameter) Cast iron.

Part number 1288835

Fits 1936 60-80 Series 1937-38-39 80 Series

- Big Series sparkplug cover
- Generator mounting bracket
- Rear fenders, left & right (1938-39-40 Series 80-90)
- · Two hub caps

Jari Vuorinen

Mantypolku 5

47710 Jaala

FINLAND

Fax: 358 5 3634508

E-mail: perhe@iobox.fi

Parts WANTED

1937 PARTS WANTED:

For 1937 Limited need: • Wheel Rims • Front Brake Drums • Front Suspension Pins and Bushings.

*Doc Scantlin (#1150) 2824 Ridge Road, Huntingtown, MD 20639

Phone: (301) 855-9102 E-mail: doc@docscantlin.com

Gars FOR SALE

· TWO 1937s FOR SALE:

 1937 Century Coupe, runs good, 98% complete, some rust.

\$6.500. or

\$8,000. with sidemounts

1937 Century 4-Door sedan Model 61.
 Solid and straight. Runs and drives good.

\$4500. or

\$6,000. with sidemounts

Dave Tacheny (#997) 11949 Oregon Ave. N.

Champlin, MN 55316 (612) 427-3460

1938 CENTURY PICK-UP FOR SALE:

1938 Century Custom Pick-Up Truck (See March/April, 2000 Torque Tube)
All oak wood floor and outside trim. Radio, heater, window fan, tan leather interior, beige paint. Accessories: front bumper badge, grille guard, driving light, fender guides, dual outside mirrors, sun visor, rear turn signals (arrows). Have complete history since new.

\$19,750.

firm to 37/38 Club members until 3/30/01

\$22,750. to non-members

George Belanger, PO Box 256 Winthrop Harbor, IL 60096-0256

Phone: (847) 731-8224

1938 SPECIAL FOR SALE:

1938 Special Coupe Model 46

Needs total restoration. Car is complete but needs lots of work.

\$2500.00. O.B.O.

John Baine (#1090)

Bradford, Ontario, Canada

Phone: (905) 775-2622

· 1937 SPECIAL FOR SALE:

Dark Green 1937 Special Sedan.

Estate Sale. All original. The car was shown in the Philadelphia area before retirement to Florida by owner. Was in good running condition when garaged 3 years ago in Blounstown, Florida. Asking \$20.000. or best offer

Call Joan Amoroso at: (610) 924-0494 - if no answer leave call back number and best time to reach you.



FOR SALE - 1937 CENTURY 60C:

1937 Century 4-Door Convertible Sedan Model 60C. Body off restoration some years ago. A beautiful maroon car. 410 made, 11 exported. Has vinyl interior. Some minor paint chips.

\$32,500. obo

Bob Ankenney (#1116) Box 208 La Mirada, CA 90637

Phone: (714) 449-0114



1937 CENTURY FOR SALE:

Black 4-Door Trunk Back Sedan Model 61. Original tan interior. New wide whitewall tires. Original 37 Calif. plates. Fog lights. Runs great. Extras in trunk: Rebuilt Stromberg carburetor, manuals, fog lights, car cover. \$7,500.

Steve Nathanson (#656) 69 Terrace Rd.

Walnut Creek, CA 94596 Phone: (925) 947-6711

E-mail: MY37BUICK@aol.com

1938 SPECIAL FOR SALE:

4-Door Trunk Back Sedan Model 41. Tan with brown interior. wide-white-wall tires, radio. heater, clock, push-button starter, oil filter. Good condition, runs great. An excellent 20 footer. \$7.500.

Ben Jarvis (#1181)

923 Devore Rd.

Devore, CA 92407

Home Phone: (909) 880-8975 Office Phone: (909) 823-8000



1937 ROADMASTER WANTED:

4-Door Trunk Back Sedan Model 81 with low mileage. Recent restoration in number 2 or better condition. Also want a 1937 Limited, any model, in number 2 or better condition.

John Welby (#1497) 1665 Shipman Rd.

Oxford, MI 48371

Phone: (248) 628-8787

CENTURY WANTED:

1938, 1939 or 1940 Century. Car must be drivable.

Walter Lapic (#999)

682 Rt. 68

New Brighton, PA 15066

Liturature FOR SALE

	6100
•1937 color catalog, 15 x 7, 32 p,	. \$100.
*1037 color folder	545.
•1937 factory photos 8 x 10, b & w 90 Limo, 2 dit	9 each.
•1937 used car invoice, 40 sedan,	\$10.
•1037 June "Ruick Magazine"	\$15.
•1937 mailer large non-color folder, "Buick Again!", 4 models shown,	530.
•1937 owner's manual	500.
*1037 owner's manual also lube chart owner ID card mint	575.
•1937-38 shop manual, Fisher Body, also Cadillac, LaSalle, Chevy and Pontiac	\$65.
•1938 color catalog, 11 x 8, 32 p, plus covers,	202.
•1938 color folder, full line,	\$40.
*1038 factory mailing envelope	\$10.
•1938 factory photo, 8 1/2 x 13 1/2. Eight sedan, cut out in shape of car	\$18.
•1938 factory photo model 47 sedan	\$12.
•1938 factory photo 8 x 10 model 40C convertible.	512.
•1938 wooden nickel, "Buick Buck", Harrisburg Jamboroo,	\$25.
•1038? owner service policy	518.
•1938 salesman's card. lists models, prices, accessories, 10/5/37,	\$15.
•1938 non color folder. "News"	\$30.
•1938 non color folder, "News",	\$15.
•1938 owner's manual	\$60.
•1938 owner's manual,	\$25.
•1938 part color catalog, 8 x 4 1/2, 12 p, "Safety Cushions", Torque-Free Springing features	\$18.
•1938 shop manual, self shifting transmission, series 40,	\$40.
•1938 shop manual, supplement, self-shifting transmission, series 40, soiled	\$40.
•1936-39? dealer blotter,	\$15.
•1936-39? matchbook,	\$12.
*1936-39 cardboard fan give-away from Bess Funeral Home, Chicago, IL, shows Buick cars,	\$35.
•1939 color catalog,	\$85.
•1939 color folder, full line,	
*1939 factory mailing envelope,	\$10.
•1939 factory photo, 8 x 10, Century 4-dr touring sedan,	\$12.
*1939 "Buick Magazine", show issue, all models in color,	\$50
*1939 "Buick Magazine", Jan, March, April, May, July, Nov, Dec,	5 each.
•1939 wooden nickel, 1 1/2", "Harrisburg Jamoroo-One 1939 Buck",	\$20
•1939 factory book, 8 1/2 x 11, 124 p, "Buick Parts and Service Bulletins",	
abridged edition VI, Sept 1, 1938 to Aug 4, 1939, softbound,	\$75
•1939 non color folder, "Big News",	\$30
•1939 owner's manual,	
•1939 owners manual,	500.

WALTER MILLER

6710 BROOKLAWN PKWY, SYRACUSE, NEW YORK, 13221 USA PHONE: (315)432-8282 FAX: (315)432-8256 www.autolit.com

Liturature WANTED

WANTED: TORQUE TUBE BACK ISSUES

• Vol: XI All • Vol: XII All except #2 and #6 • Vol: XIII All except #6 • Vol: XIV #1 and #2

Sverre Christofferson (Norway)

E-mail: sverrech@online.no

1938 BUICK SPECIALS BY VICTORY MODELS





CATALOG \$2.00

VISA

VL-1 1938 BUICK SPECIAL SEDAN

VL-2 1938 BUICK SPECIAL BUSINESS COUPE

Additional BODY STYLES coming including a TAXI − Also coming soon a 1940 Bunck Super − SHIPPING \$6.00 first model, € \$1.00 each additional model Send Inquiries and Checks Payable to

RAY PASZKIEWICZ, JR. P.O. BOX 156, CLARKSBURG, N.J. 08510 . TEL. 732-446-9381

FAX 732-446-09297



1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED. Complete Research Package \$50.00, \$60.00 if shipped outside the USA. Additional information available at http://www.OldBuickArchive.com. Also check out 1937 and 1938 in the "Valve-In-Head Archive" at the web site for a listing of reference material that can be photo copied for research purposes.

1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



ERRY DUNHAM AUTOMOTIVE RESEARCH SERVICES



P.O. Box 4057, Apopka, Florida 32704-4057 e-mail: Buickohv@aol.com . web site: www. OldBuickArchive.com

1937-38 BUICK





DOORWEA	THERSEAL-SPONGE		
Glue-in	DW-378	\$1,90	ft.
Clip-in	DW-80	\$3.50	ft.
Clips	WC-80	\$0.75	ca.







.....53.50 ea.







ENDS \$192, Center \$192. Valve Body \$199






































































\$100 and up.....


LICENSE PLATE FRAMES. Chromed Brass LF-333P...... \$62.00 Pair





.\$27.00





Tie Rod End...



BOB'S AUTOMOBILIA BOX 2119 ATASCADERO, CA 93423 TELEPHONE (805) 434-2963 VISA - MASTERCARD - DISCOVER or C.O.D. CATALOG #47 \$5.00 or ONLINE at www.bobsautomobilia.com

BUICK...Upholstery and Top Kits 1927/1955

Since 1977.. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits, Seat Upholstery, Tops and related accessories as well as "era" fabrics by the yard. Inquire Toll Free

1-888-388-8726



Tel 978-388-8047



Restoration and repairs that are correct and authentic.


"I know your Buick." Former Director of Long Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945



2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast STEERING WHEELS Call or write for brochure



RESTORATION



Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927 thru 1953

AUTHENTIC REPRODUCTION WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE FINEST MATERIALS

EACH SUPPLIED WITH: LIMITED WARRANTY

INSTALLATION INSTRUCTIONS

SCHEMATICS

ALSO OFFERING:

WIRING SUPPLIES

CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087

